





RYB 3PHASE AC POWER SUPPLY












**Control Circuit Diagram of Automatic Star Delta (Y-Δ) starter with Timer for 3-Phase Motor.**





INFORMATION ON THIS  
DOCUMENT IS CREATED BY  
LEW-HAMMER. IT IS  
CLOSED IN CONFIDENCE



<b>44</b>	Cutler-Hammer
TIME PVNR Size 1 & 2 with Solid State Overload	